

# Inspection Photos

February 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334610

Location Name: BASS-67S93W/14SWNE

Inspection Document #: 702801267

Garfield County, CO

SWNE Section 14 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: BASS-67S93W/14SWNE

Location ID: 334610



**Photo 1.** Photo shows a tank drain is not bullplugged.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801267

Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



**Photo 2.** Photos show staining below a produced water/condensate tank drain.



Inspection Photos  
Location Name: BASS-67S93W/14SWNE  
Location ID: 334610



**Photo 3.** Photo shows piping at the tank battery is open ended and lacks BMPs to prevent wildlife entry.