

Inspection Photos

February 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334635

Location Name: PARKER-67S93W/15NESE

Inspection Document #: 702801270

Garfield County, CO

NESE Section 15 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PARKER-67S93W/15NESE
Location ID: 334635



Photo 1. Photo taken from the entrance shows an overview of the location.

Inspection Photos
Location Name: PARKER-67S93W/15NESE
Location ID: 334635



Photo 2. Photo shows storage of a trailer on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801270

Inspection Photos
Location Name: PARKER-67S93W/15NESE
Location ID: 334635



Photo 3. Photos show production areas. A tank battery sign is absent (left).



Inspection Photos
Location Name: PARKER-67S93W/15NESE
Location ID: 334635



Photo 4. Photo shows an example of interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801270