

Inspection Photos
Location Name: PETERSON-65N63W/30SWNE
Location #: 309818



Photo #1
Peterson 30-51 (123-25421) Wellsite
Temporarily Abandoned | TA



Photo #2
Peterson CX GH 30-14D, 30-41D, 30-26D, 30-40D, 30-28D, Peterson 30-31, 30-32, 30-41, 30-42, 30-51.
Battery site
Inactive | Shut-down
Equipment documented: Loc. # 430376