

Inspection Photos
Location Name: PETERSON-65N63W/30NENE
Location #: 309819



Photo #1

Peterson 30-41 (123-25422) Wellsite
Temporarily Abandoned | TA



Photo #2

**Peterson CX GH 30-14D, 30-41D, 30-26D, 30-40D,
30-28D, Peterson 30-31, 30-32, 30-41, 30-42, 30-51.**

Battery site

Inactive | Shut-down

Equipment documented: Loc. # 430376