

Interim Reclamation and Stormwater Inspection

February 10, 2023

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697504507

Weld County, CO

NENE Section 29 T11N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 1. Photo taken along a portion of the southern interim reclamation area, facing South. Photo illustrates Cereal rye that appears to have gone to seed. At the time of this inspection, Cereal rye growth appeared to be limited to southern interim reclamation area.



Photo 2. Photo taken from the eastern interim reclamation area, facing West. Photo illustrates the interim reclamation area.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 3. Photo taken from the central location, facing West. Photo illustrates Operator is storing equipment/supplies on location. This was previously observed back in June 2022.

