


## Inspection Photos

Location Name: 31-4-64 SWSW Ocoma Tank Battery

Facility ID: 468054



**Photo #1 Appears to have gas flowed today 2-21-23**



**Photo #2 Appears to have gas flowed yesterday 2-20-23**



## Inspection Photos

Location Name: 31-4-64 SWSW Ocoma Tank Battery

Facility ID: 468054



**Photo #5 Balon valves at the separator appear to be open**

**Photo #6 Balon valve appears open going into the separator**

## Inspection Photos

Location Name: 31-4-64 SWSW Ocoma Tank Battery

Facility ID: 468054



**Photo #7 Riser for sales gas appears to be open**