

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2023

Submitted Date:

02/22/2023

Document Number:

699106522**FIELD INSPECTION FORM**Loc ID 468051 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468054	TANK BATTERY	AC	09/26/2019		-	31-4-64 SWSW Ocoma Tank Battery	AC

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment: [Appears to have sold product. See attached photos.](#)Corrective Action: [Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863](#)

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 468054 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 2/21/23 at approximately 1520hrs, I, Inspector Adam Burns, Conducted an on-site inspection at 31-4-64 SWSW Ocoma Tank Battery of KP Kauffman Company inc, at Facility ID: 468054 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Appears to have sold product. Immediately cease all gas sales pursuant to Order 1V-863.</p> <p>Further gas sales from this battery is a violation of Rule 219 and Order 1V-863</p> <p>Wells that flow into this facility include the following:</p> <p>-OCOMA 31-18 "API # 05-123-14803"</p> <p>-OCOMA 31-19 "API # 05-123-14917"</p> <p>-OCOMA 31-17 "API # 05-123-15026"</p> <p>-OCOMA 31-20 "API # 05-123-15271"</p> <p>-OCOMA 31-25 "API # 05-123-15677"</p> <p>-OCOMA 31-26 "API # 05-123-17417"</p> <p>-OCOMA 31-27 "API # 05-123-17806"</p> <p>They all feed into one Separator on location.</p> <p>Gas Meter Station ID: 045201</p> <p>GPS Coordinates for gas meter: 40.2615, -104.6214</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	02/22/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106523	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6029372