



99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

(C)

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100☐ NOTICE OF SATISFACTORY INSPECTIONAPI No. 05 061 - 6154LEASE NAME: PYLES #3LOCATION: NWNW10-19S-45WOPERATOR: WESTERN O.P.DATE: 11-16-98INSPECTOR: R. Van SickleInsp. Type: FDInsp. Status: TA

PA: Y

(N)Pass/Fail: P (F)

Viol: Y

N

NOV: Y

(N)

## INSPECTION ITEM

## COMMENTS

## INPUT

<b>Well ID Signs</b> (Rule 210, 604.c(4))	<u>None</u>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	<u>None</u>	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	<u>None</u>	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	<u>None</u>	✓
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	<u>N/A</u>	
<b>General Housekeeping</b> (Rule 603)	<u>OK</u>	
<b>Spills (Oil/Water)</b> (Rule 907)	<u>None</u>	
<b>Bradenhead</b> (Rule 207.b)	<u>—</u>	
<b>Drilling Well/Workover</b> (Rule 317)	<u>—</u>	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<u>—</u>	
<b>Miscellaneous</b>	<u>Csg swedged to 2".</u>	✓

CORRECTIVE ACTION REQUIRED: MITB Produce or plug

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

