

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334649

Location Name: GMR-67S93W/3SWSW

Inspection Document #: 702801282

Garfield County, CO

SWSW Section 3 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GMR-67S93W/3SWSW  
Location ID: 334649



**Photo 1.** Photo taken from the northeast shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801282

Inspection Photos  
Location Name: GMR-67S93W/3SWW  
Location ID: 334649

2/17/23  
+39.469079,-107.768860  
265° W



**Photo 2.** Photo shows drain line bull plugs installed.

