

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334615

Location Name: GMR-67S93W/9NENW

Inspection Document #: 702801286

Garfield County, CO

NENW Section 9 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GMR-67S93W/9NENW  
Location ID: 334615



**Photo 1.** Photo taken from the entrance shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801286

Inspection Photos  
Location Name: GMR-67S93W/9NENW  
Location ID: 334615



Photo 2. Photos show production areas. A tank battery sign is absent (left).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801286