

Inspection Photos

API: 071-09455

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/21/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09455 | Date: 2/21/2023

Inspection Photos



Photo 1. Facing north along the access road which is rutted and eroded in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09455 | Date: 2/21/2023

Inspection Photos



Photo 2. Stormwater water which is directed to this area from the wellsite above is causing erosion of the access road in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09455 | Date: 2/21/2023

Inspection Photos



Photo 3. There is an erosion channel along the access road ascending to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09455 | Date: 2/21/2023

Inspection Photos



Photo 4. Facing west toward the wellsite. Sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09455 | Date: 2/21/2023