

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802

Feb 22, 2023 at 1:53:52 PM
40.017293,-104.888932
Veld County
COGCC



Pic 3. Spoke with KPK supervisor and was informed they were thawing lines on the gas meter run due to freezing issues, and changing oil in other equipment.

Feb 22, 2023 at 2:09:32 PM
40.014850,-104.888526
Veld County
COGCC



Pic 4 tanker truck unloading fluid from tanks on location.