

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



**Photo #9070 From entrance to location.**



**Photo #9071 From entrance to location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #9072 From entrance to location.




Photo #9073 Chemical tank missing required information.