

Inspection Photos
Location Name: Strong 4-22
Location ID: 332567



Photo 1: Tank Battery Sign



Photo 2: Sales of gas

Inspection Photos
Location Name: Strong 4-22
Location ID: 332567




Photo 3: Sales



Photo 4: Valves appear to be open

Inspection Photos
Location Name: Strong 4-22
Location ID: 332567



Photo 5: Valve appears to be open



Photo 6: Valve appears to be open