

Inspection Photos

Location Name: Strong 1-7, 3-15, 2-8

API #: 05-123-11406, 05-123-11661, 05-123-11391



Photo 1: appears to have sold product



Photo 2: Valves appear to be open



Inspection Photos

Location Name: Strong 1-7, 3-15, 2-8

API #: 05-123-11406, 05-123-11661, 05-123-11391



Photo 3: Valves appear to be open



Photo 4: Valves appear to be open

Inspection Photos

Location Name: Strong 1-7, 3-15, 2-8

API #: 05-123-11406, 05-123-11661, 05-123-11391



Photo 5: Valve appears to be open