

Location ID: 475652



Inspection Photos
Location Name: Carl A Miller Sub Battery
Location ID: 475652




Photo #3 Gas Meter Calibration Card



Photo #4 Balon valve on down stream side appears to be open

Inspection Photos
Location Name: Carl A Miller Sub Battery
Location ID: 475652



Photo #5 Balon valve on the upstream side appears to be open



Photo #6 PSI appears to be on the sales gas line from psig

Inspection Photos
Location Name: Carl A Miller Sub Battery
Location ID: 475652



Photo #7 placement of psig on sales line



Photo #8 psig appears to so pressure on flowline at the separator

Inspection Photos
Location Name: Carl A Miller Sub Battery
Location ID: 475652



Photo #9 psig appears to show pressure on the separator



Photo #10 Balon valve appears to be open

Inspection Photos
Location Name: Carl A Miller Sub Battery
Location ID: 475652



Photo #11 Ball valve appears to be open on the top side of the separator




Photo #12 Balon valve on the inlet to the separator appears to be open