

Inspection Photos

Location Name: Facility 5
Facility ID: 478836




Photo #1 Sign



Photo #2 Sign

Inspection Photos
Location Name: Facility 5
Facility ID: 478836



Photo #3 Valves appear to be open




Photo #4 Trucking companies log showing crude oil is being delivered to Whitecliffs Pipeline

Inspection Photos
Location Name: Facility 5
Facility ID: 478836



Photo #5 Trucking company transporting crude oil product



Photo #6 Trucking company hooked up and pulling crude oil product on location