

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334766

Location Name: GMR-67S93W/9SESW

Inspection Document #: 702801291

Garfield County, CO

SESW Section 9 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GMR-67S93W/9SESW  
Location ID: 334766



**Photo 1.** Photos show production areas. A tank battery sign is absent (left).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801291

## Inspection Photos

Location Name: GMR-67S93W/9SESW

Location ID: 334766



**Photo 2.** Photos show production areas.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 702801291