

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334678

Location Name: GMR-67S93W/9SESW

Inspection Document #: 702801293

Garfield County, CO

SESW Section 9 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GMR-67S93W/9SESW  
Location ID: 334678

2/17/23  
+39.455869,-107.783441  
19° N



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: GMR-67S93W/9SESW  
Location ID: 334678



Photo 2. Photos show production areas. A tank battery sign is absent (left).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801293

Inspection Photos  
Location Name: GMR-67S93W/9SESW  
Location ID: 334678



Photo 3. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801293

Inspection Photos

Location Name: GMR-67S93W/9SESW

Location ID: 334678



**Photo 4.** Photo shows perennial grasses established on slopes. No other areas are visible due to snow cover.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801293