

Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334584

Location Name: HMU-67S93W/9SWNW

Inspection Document #: 702801295

Garfield County, CO

SWNW Section 9 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HMU-67S93W/9SWNW
Location ID: 334584



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: HMU-67S93W/9SWNW
Location ID: 334584



2/17/23
107.784740
274° W



Photo 2. Photos show production areas. A tank battery sign is absent (left).

