

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 335030

Location Name: HMU FEE-67S93W 9SWNW

Inspection Document #: 702801297

Garfield County, CO

SWNW Section 9 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: HMU FEE-67S93W 9SWNW

Location ID: 335030



**Photo 1.** Photo taken from the south shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801297

Inspection Photos

Location Name: HMU FEE-67S93W 9SWNW

Location ID: 335030



2/17/23  
7,-107.784740  
274° W



Photo 2. Photos show production areas. A tank battery sign is absent (left).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801297