

Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334924

Location Name: HMU-67S93W/10NENE

Inspection Document #: 702801299

Garfield County, CO

NENE Section 10 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HMU-67S93W/10NENE
Location ID: 334924



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: HMU-67S93W/10NENE
Location ID: 334924




Photo 2. Photos show production areas. A tank battery sign is absent (left).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801299

Inspection Photos
Location Name: HMU-67S93W/10NENE
Location ID: 334924



Photo 3. Photos show examples of interim areas. Introduced perennial grasses and native shrubs appear established.

