

Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334921

Location Name: HMU-67S93W/10NWNE

Inspection Document #: 702801301

Garfield County, CO

NWNE Section 10 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HMU-67S93W/10NWNE
Location ID: 334921



Photo 1. Photo taken from the north shows an overview of the location.

Inspection Photos
Location Name: HMU-67S93W/10NWNE
Location ID: 334921



Photo 2. Photos show production areas. A tank battery sign is absent (left).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801301

Inspection Photos
Location Name: HMU-67S93W/10NWNE
Location ID: 334921



Photo 3. Photos show examples of interim areas. Introduced perennial grasses and native shrubs appear established.

