

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334961

Location Name: BENZEL-67S93W/1SWSW

Inspection Document #: 702801305

Garfield County, CO

SWSW Section 1 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-67S93W/1SWSW  
Location ID: 334961



**Photo 1.** Photo taken from the entrance shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801305

Inspection Photos  
Location Name: BENZEL-67S93W/1SWSW  
Location ID: 334961



**Photo 2.** Photo shows old injection line debris has been removed.

