

# Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334829

Location Name: BENZEL-66S93W/36SESW

Inspection Document #: 702801307

Garfield County, CO

SESW Section 36 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



**Photo 1.** Photo taken from the entrance shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801307

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



Photo 2. Photo shows caps installed on piping.

