

Inspection Photos
Location Name: NRC- Rocky Mountain Fuel 9-9-15H
Facility ID: 421286




Photo #1 Sign

Photo #2 Gas Meter Calibration Card

Inspection Photos
Location Name: NRC- Rocky Mountain Fuel 9-9-15H
Facility ID: 421286



Photo #3 Gas Production as of today 2-23-23

Photo #4 Gas production produced yesterday 2-22-23

Inspection Photos

Location Name: NRC- Rocky Mountain Fuel 9-9-15H

Facility ID: 421286



February 23, 2023 at 9:58 AM
+40.0639,-104.8866
19° N
Weld County
Colorado Oil & Gas Conservation Commission



February 23, 2023 at 9:58 AM
+40.0639,-104.8866
7° N
Weld County
Colorado Oil & Gas Conservation Commission

Photo #5 Inlet Balon valve appear to be open

Photo #6 Inlet Balon valve appear to be open

Inspection Photos
Location Name: NRC- Rocky Mountain Fuel 9-9-15H
Facility ID: 421286



Photo #7 Top-side ball valve appears to be open

Photo #8 gas meter run ball valve on upstream appears open