

Inspection Photos  
Location Name: North York #11-12  
Location ID: 319889



Colorado Oil and Gas Conservation Commission  
39.979, -104.95039, 1533.0m  
Feb 24, 2023 10:26:50 AM

Photo1 production equipment



Colorado Oil and Gas Conservation Commission  
39.97897, -104.95042, 1527.0m  
Feb 24, 2023 10:26:27 AM

Photo 2 Meter flow rate

Inspection Photos  
Location Name: North York #11-12  
Location ID: 319889



Photo 3 flow time