

Inspection Photos

API: 071-07252

Operator: [OGRIS OPERATING LLC](#)

Inspection Date: 2/23/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07252 | Date: 2/23/2023

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07252 | Date: 2/23/2023

Inspection Photos



Photo 2. There is ice buildup at the wellhead indication a dripping leak.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07252 | Date: 2/23/2023