

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403333043

Date Received:

02/28/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Mike Storey

Phone

970-939-6353

Email

mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696304695

Inspection Date: 02/09/2023

FIR Submit Date: 02/10/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 422681

Location Name: State Antelope Number: 11-2HZ County: WELD

Qtrqr: LOT4 Sec: 2 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.435490 Longitude: -104.298420

FACILITY - API Number: 05-123-00 Facility ID: 422689

Facility Name: State Antelope Number: 11-2HZ

Qtrqr: LOT4 Sec: 2 Twp: 5N Range: 62W Meridian: 6

Latitude: 40.435490 Longitude: -104.298420

CORRECTIVE ACTIONS:

1 CA# 167368

Corrective Action: Install sign to comply with Rule 605.f.

Date: 03/10/2023

Response: CA COMPLETED

Date of Completion: 02/24/2023

Operator Comment: Updated and installation of labels for Water Tanks was completed on 2/24/2023 to comply with Rule 605.f.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up completed for location.

Important Note: Operator listed a second CA for the location; however, the CA was not identified on the Inspection Form (only 1 CA was noted on the Inspection Form). The second CA: Riser at North Separator will need to be marked to be in compliance with Rule 606. Operator did address this CA and provided follow-up photos and notes. These photos and notes have been included on the attached "Inspection Photos" PDF report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 2/28/2023 1:26:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

403333048	Inspection Photos
-----------	-------------------

Total Attach: 1 Files