

# Inspection Photos

2/28/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334359

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334359



February 27, 2023



February 27, 2023

**Photo 1:** Photos taken from the central working pad area, facing east. Photo left shows stormwater ponding on the working pad area. Photo right shows drain connected to the perimeter stormwater diversion ditch; drain has been repaired; BMPs remain missing or insufficient to allow for proper stormwater discharge from the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334359



February 27, 2023



February 27, 2023

**Photo 2:** Photos examples showing Undesirable Plant establishment and Weed debris observed within the perimeter stormwater diversion ditch.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334359



**Photo 3:** Signage at tank battery.