

Caerus Piceance LLC

LR 6G Pad

Location #335727



Entrance to location



Sign at tank battery

Caerus Piceance LLC
LR 6G Pad
Location #335727



Debris



No tank capacity

Caerus Piceance LLC
LR 6G Pad
Location #335727



Chemical pump trough full




Chemical pump trough full

Caerus Piceance LLC
LR 6G Pad
Location #335727



Unused equipment



Unused equipment

Caerus Piceance LLC
LR 6G Pad
Location #335727



Unused equipment



Debris

Caerus Piceance LLC
LR 6G Pad
Location #335727



Tank hooked up to wellhead



Tank hooked up to wellhead