



Inspection Photos
Location Name: Gasper 11-1
Location ID: 320468



Photo#1 Production Tank/Produced Water Tank

Photo#2 Separator/Gas Meter

Location ID: 320468



Photo#3 Wellhead




Photo#4 Netting on produced water tank in disrepair

Inspection Photos
Location Name: Gasper 11-1
Location ID: 320468



Photo#5 Netting on produced water tank in disrepair



Photo#6 Stained Soil