

# Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334138

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334138



**Photo 1:** Photos taken from the west end of the Location, facing northeast to southeast. Photos provide an overview of the Location. Photos also examples showing BMPs to stabilize the working pad, and to minimize degradation, tracking and off-site sediment transport are missing or insufficient.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334138



February 27, 2023



February 27, 2023

**Photo 2:** Photos example showing BMPs to stabilize the working pad, and to minimize degradation, tracking and off-site sediment transport are missing or insufficient.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334138



February 27, 2023

**Photo 3:** Wildlife carcass at Location entrance.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources