

**Caerus Piceance LLC
RNP 197-15A2H Pad
Location #441601**



From entrance to location



From entrance to location

**Caerus Piceance LLC
RNP 197-15A1 Pad
Location #441601**




From entrance to location



Chemical tank lacks proper labeling



**Caerus Piceance LLC
RNP 197-15A2H Pad
Location #441601**



**Sign at tank battery South edge. Sec 15 at wellhead &
on database. Access by County Road 5.**

Sign at tank battery West edge



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
RNP 197-15A1 Pad
Location #441601




Debris



Hoses not in use.



Caerus Piceance LLC
RNP 197-15A1 Pad
Location #441601



Hoses not in use



Unused equipment