

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Gas Meter Run	# 1		
Comment:	Appears to have sold product. Total flow was not working. See attached photos.		
Corrective Action:	Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863		Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 475652 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 2/23/23 at approximately 0900hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Carl A Miller Sub Battery of KP Kauffman Company inc, at Facility ID: 475652 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Appears to have sold product. Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863 All balon valves appear to be open on separator and gas meter line. Pressure appears on separator and gas meter lines by psig. Total flow box for gas measurement was not working. Wells that flow into this facility include the following: - MILLER #13-5 "API # 05-123-15954" - CARL A MILLER B #13 "API # 05-123-09655" - CARL A MILLER B #3 "API # 05-123-07602" - CARL A MILLER B #4 "API # 05-123-07681" - CARL A MILLER B #5 "API # 05-123-07704" - CARL A MILLER B #7 "API # 05-123-08702" - CARL A MILLER B #9 "API # 05-123-08971" - CARL A MILLER B #10 "API # 05-123-08978" - CARL A MILLER B #11 "API # 05-123-08979" - CARL A MILLER B #12 "API # 05-123-09051" - CARL A MILLER B #14 "API # 05-123-12831" - CARL A MILLER E #1 "API # 05-123-13534" - CARL A MILLER B #1 "API # 05-123-07579" - CARL A MILLER B #2 "API # 05-123-07597" - CARL A MILLER B #6 "API # 05-123-07713" - CARL A MILLER B #8 "API # 05-123-08970"</p> <p>They all feed into one Separator on location.</p> <p>Gas Meter Station ID: 45422 GPS Coordinates for gas meter: 40.0754, -104.9107</p> <p>See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	02/23/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403329368	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031701

699106525	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031696
-----------	-------------------	---