

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 3 ancillary equip.



Photo 4 pump jack

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748




Photo 5 TB sign.

Photo 6 TB.

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 7 HHS.

Photo 8 Gas Meter Run

Inspection Photos
Location Name: McCrumb 1
Location ID: 317748



Photo 9 PW vault.