

Inspection Photos

API: 061-06743

Operator: WESTERN OPERATING COMPANY

Inspection Date: 3/1/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 3/1/2023

Inspection Photos



Photo 1. Facing north toward the abandoned wellsite. There is gravel and debris that remains which should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 3/1/2023

Inspection Photos



Photo 2. The well sign remains along with gravel and debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 3/1/2023

Inspection Photos



Photo 3. There are four markers and anchors that remain at the location which should have been removed with 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06743 | Date: 3/1/2023