

Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #422301

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



Photo 1: Photos 1-2 provide an overview of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



February 27, 2023



February 27, 2023

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



Photo 3: Unused equipment.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



Photo 4: Unused equipment required to be removed per Inspection # 699804777



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



Photo 5: Tank battery on the NW end of the Location. Battery missing signage per 605.e.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #422301



February 27, 2023



February 27, 2023

Photo 6: Photos examples showing reclamation on the berms of the Location; vegetation establishment evident, though it does not appear to be uniform per 1003 rules. A follow-up inspection in the future growing season will be needed to determine compliance with 1003 rules.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #422301



Photo 7: Photos examples of interim areas on the Location; areas appear to be progressing towards 1003 standards. Limited inspection due to winter conditions.