

Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #440705

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show areas of the Location not reasonably needed for production, requiring 1003 reclamation.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



February 27, 2023



February 27, 2023

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



February 27, 2023



February 27, 2023

Photo 3: Photos 3-4 provide examples showing BMPs to minimize degradation, tracking and off-site sediment transport are missing or insufficient on the working pad areas of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #440705




Photo 4: See comments under photo 3

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #440705



Photo 5: Photo taken from the wells. Photo shows stormwater runoff due to snowmelt flowing into the wellhead cellars on the Location. Additional BMPs to allow for proper discharge required.



February 27, 2023

Photo 6: Photo shows stormwater runoff draining into wellhead cellar.



February 27, 2023