

Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 3/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 1. Facing south toward the access road. Topsoil is being hauled in for recontouring of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023

Inspection Photos



Photo 2. The electric powerline which dead ends at the location must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 3/1/2023