

COLORADO OIL



IN COMMISSION

99999999
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- (061 06108)		LEASE NAME: SPRING WEAR #2	
LOCATION: SWSE5-195-45W		OPERATOR: WESTERN OP.	
DATE: 11-13-98		INSPECTOR: R. Vansickle	
Insp. Type: ID	Insp. Status: TA	PA: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input checked="" type="radio"/> Viol: Y <input checked="" type="radio"/> N <input checked="" type="radio"/> NOV: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	✓	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	None	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	None	
Tank Battery Equipment (Rule 603.b.3, 604)	None	✓
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	N/A	
General Housekeeping (Rule 603)	OK	
Spills (Oil/Water) (Rule 907)	None	
Bradenhead (Rule 207.b)	—	
Drilling Well/Workover (Rule 317)	—	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	—	
Miscellaneous	—	

CORRECTIVE ACTION REQUIRED: MIT or plug

Date Corrective Action Required By: 1-1-99

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00572482

White - File Canary - Operator Pink - Well Site

Oil "produced" from this 7/18/89
disposal well will be allocated
back to the various leases the water
was produced from. Permian will
be purchasing the oil from this
tank. Transporter for other leases
Diamond Shamrock. Per MP &
ED this is not a problem. *QR*

fehl
Form Security
Neutral Possibly
KB. 3872
AL. 3863