



## COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 25 API# 061 06108 0 INSPECTOR L. Robbins DATE 11/7/89WELL NAME SALTWATER DISPOSAL 2 TYPE D SITE INSPECTION X

FIELD 7500 BRANDON STATUS AC WITNESS MIT

OPER 67240 PARK OIL &amp; GAS INC

LOCATION SWSE 5 19.0S 45.0W 6

MAX PERMITTED PRESS 1490 PSI DATE LAST INSPECTION 12/13/88 OUTCOME A

LAST REPORTED PRESS PSI 08/89 DATE LAST MIT 05/14/87

WELL RESTRICTIONS

REMEDIAL ACTION

COMPLETION TYPE TP

## TUBING PRESSURE

ZONE ABCK MSSP

MIT \_\_\_\_\_ INJECTING 0 (VAC) PSI

MIT \_\_\_\_\_ NOT INJECTING \_\_\_\_\_ PSI

TUBING-CASING ANNULUS 0 PSIBRAIDENHEAD 0 PSIP E R F S  
TOP 4890 4773  
BOT 5583 4860

## MECHANICAL INTEGRITY TEST

0 MIN. \_\_\_\_\_ PSI

5 MIN. \_\_\_\_\_ PSI

10 MIN. \_\_\_\_\_ PSI

15 MIN. \_\_\_\_\_ PSI

PRESS CHANGE \_\_\_\_\_ PSI

CHART USED - YES \_\_\_\_\_ NO \_\_\_\_\_

MIT  
PACKER  
DEPTHCASING  
SIZE 9 5/8  
DEPTH 177SIZE 7 /  
DEPTH 5610SIZE /  
DEPTHSIZE /  
DEPTH

PACKER 4700

LINER  
TOP  
SIZE /  
DEPTHPBTVD 5591  
TVDACCEPTABLE X NOT ACCEPTABLE \_\_\_\_\_REMARKS: Backside and bradenhead  
were dead when opened.  
Passed site inspection.  
J. Robbins