

Operator: CRESTONE PEAK RESOURCES

Location Name: RUSH 4-65 29-30 3AH

Loc ID: 449806

Inspection: 706700165



Exhibit A

CA: No tank battery sign on either one. Install sign to comply with Rule 605.e.

CA Resolution: Signage has been installed to comply with Rule 605.e.