

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1460 From entrance to location.



Photo # 1461 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1462 From entrance to location.



Photo # 1463 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1464 Location



Photo # 1465 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1466 GM 424-34 Wellhead sign illegible



Photo # 1467 Battery sign illegible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1468 Open ended load line



Photo # 1469 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1470 Open ended load line



Photo # 1471 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1472 Open ended load line



Photo # 1473 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 23-34

Location # 335302



Photo # 1490 Transport of sediment & degradation of vegetation



Photo # 1489 Transport of sediment & degradation of vegetation