

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1653 From entrance to location.



Photo # 1655 Location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1656 Location



Photo # 1668 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1658 Open ended load line



Photo # 1661 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1662 Undesirable plant species



Photo # 1663 Undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1664 Undesirable plant species



Photo # 1665 Undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 22-2 Pad

Location ID: 323962



Photo # 1654 Culvert needs maintenance