

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



Photo # 1569 From entrance to location



Photo # 1570 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



Photo # 1571 Location



Photo # 1572 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



**Photo # 1573 Sediment Trap needs maintenance**



**Photo # 1574 Sediment Trap needs maintenance**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



**Photo # 1579 Deadman improperly marked**



**Photo # 1583 Open ended load line**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



Photo # 1584 Open ended load line



Photo # 1581 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL GM 32-34 Pad

Location ID: 335164



Photo # 1582 Debris



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources