

Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Location Name: State Antelope K-1 Pad

Loc ID: 431198

Inspection: 696304679



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J



Exhibit K

CA: Unmarked Risers at Compressor Area and North Separator; Comply with Rule 606

CA Resolution: Markers/signage have been installed to comply with Rule 606.



Exhibit A



Exhibit B




Exhibit C

CA: Oily waste at Compressor. Wildlife Netting at West Day Tank has hole. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b

CA Resolution: Oily waste has been properly disposed of to comply with Rule 905.e. Wildlife protection equipment has been adequately installed and measures are in place to prevent unauthorized discharge to comply with Rule 902.b.



Exhibit A

CA: West Side of Tank - Tank #220504 - NFPA, Content, and Capacity Labels. Install sign to comply with Rule 605.h.

CA Resolution: Signage/labels have been installed to comply with Rule 605.h.