

Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1494 From entrance to location.



Photo # 1495 From entrance to location.



Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1496 From entrance to location



Photo # 1497 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Mar 2, 2023 at 1:08:55 PM
CO

Photo # 1498 Location



Mar 2, 2023 at 1:09:08 PM
CO

Photo # 1499 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1500 Location



Photo # 1505 Open ended load line



Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1513 Open ended load line



Photo # 1510 Undesirable plant species



Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1507 Containment needs maintenance




Photo # 1509 Containment needs maintenance

Inspection Photos

Location Name: TEP Rocky Mountain LLC EXXON GM 21-12 Pad

Location # 311597



Photo # 1511 Containment needs maintenance




Photo # 1514 Containment needs maintenance