

Inspection Photos

Loc: 470757

Operator: WESTERN OPERATING COMPANY

Inspection Date: 3/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 1. Facing southwest toward the PYLES offsite tank battery and storage yard.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 2. There is unused equipment being stored on location that needs to be removed. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 3. Facing west at the south side of the location. There is equipment and a vehicle that appears to have been sitting unused at this location for awhile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 4. Facing toward the PYLES offsite tank battery at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 5. There is oil stained soils at the pipe outlet and oil inside the plastic containment that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 6. The shed inside the containment battery is not maintained with metal siding laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 7. Facing back towards the PYLES tank battery. PYLES #5 wells sign is posted at the battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 8. Facing at the back side of the tank battery. There was a spill from the tank which needs to be cleaned up. The blue bucket needs to be emptied and disposed of any oil.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 9. Facing toward the southwest side of the location. There is concrete debris and a broken bottom of a tank among other debris and equipment that must be removed per Rule 606 & 1003.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 10. Facing southeast toward the PYLES offsite tank battery and storage yard. There is concrete debris and a broken bottom of a tank among other debris and equipment that must be removed per Rule 606 & 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 11. Facing northeast toward the PYLES offsite tank battery and storage yard.



Inspection Photos



Photo 12. There is various parts and supplies being stored on location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 13. There are several chemical barrals on location with faded labeling and no secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 14. There are various parts and supplies and tow buckets of oil which appear to have spilled out on the ground. Buckets of oil need to be properly disposed and stained soil cleaned up.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 15. Facing west at the north side of the location. There is storage of unused drilling pipe at the location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 16. Facing toward the east side of the location. All equipment and supplies not necessary for use on this Oil and Gas Location is prohibited per Rule 606 and 1003.a.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022

Inspection Photos



Photo 17. Facing southeast at the location PYLES offsite tank battery and storage yard. The use of this location as a storage yard is prohibited per the rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 470757 | Date: 3/1/2022