

Inspection Photos  
Location Name: Guthrie 31-2  
Location ID: 320528



Photo#1 Production Tanks

Photo#2 Separator/(2)Gas Meters/ECD/



Inspection Photos  
Location Name: Guthrie 31-2  
Location ID: 320528



Photo#3 Wellhead



Photo#4 Stained Soil below mastervlve